

This micrograph shows a cross-section of a polymer film. A dark, irregular layer is visible at the interface between the film and the substrate, indicating a region of degradation or delamination. The film itself appears relatively uniform in thickness above this interface.